



PREVENTIVE MAINTENANCE CHECKLIST

Client Name/ID: WESTNILE TV LEASED LINE

Date: 17/06/2021

Client Coordinates: 3.0176N, 30.9245E

Location: ARUA

Local Contact Personnel: DAISI

Serving Site ID: NO4160

Link Type: PTP

Serving Site Name: ZAMBIA ZONE

Preventive Maintenance Checklist	Remark/ Comment
Condition of IDU>>ODU Cable Client end: Site end:	} GOOD
Other Equipment Condition ➤ Client-end ➤ Site-end	} GOOD
Type of equipment installed	FORCE 200
Distance of Hop	1.39km
RSSI Levels (dBm)	-46
Earthing - client end	NX
Earthing - Site Radio	NX
Airlink Quality Measure ➤ Link Quality: ➤ Link Capacity:	100% 100%
Status of ODU mounting at Client end & Site	GOOD
Nature of power at client end	A.C 240V 50-60Hz
Serving site Port	ATN 26
RJ45 connectors	GOOD TERMINATION
Share link details ➤ Site name - ➤ Naming of Sector at site ➤ Other clients attached.	ZAMBIA ZONE WESTNILE TV PTP NONE

Confirm link is added to CN maestro	ADDED
<p>Check that link management is enabled</p> <ul style="list-style-type: none"> > IPS/VLAN are enabled (indicate IPS and VLAN if already existing) > SNMP is enabled > Confirm successful addition on cacti 	<p>172.19.100.57 / 29 1559</p> <p>ENABLED</p> <p>ADDED</p>

Client acknowledgment:

Name: KAJIK BAYAN

Signature: [Signature]

Date: 17-06-2021

Field Engineer:

Name: BAZARE A BEMEREKI

Signature: [Signature]

Date: 17/06/2021