2°
ELECTRICAL
DOWN TILT
Akokoro Road
Google
Nov 6, 2020 5:35:04 PM
1.9103N 32.3827E
Apac
Alenga Apac church

Alenga Roman
Catholic Church
Akokoro Road
Alengo
Google
Nov 7, 2020 2:25:22 PM
1.8496N 32.3495E
Akokoro Road
Alengo, Apac
Uganda
Alenga Roman Catholic church Apac

Alenga Roman
Catholic Church
Akokoro Road
Alengo
Google
Nov 7, 2020 2:25:32 PM
1.8496N 32.3494E
Akokoro Road
Alengo, Apac
Uganda
Alenga Roman Catholic church Apac

Alenga Roman
Catholic Church
Akokoro Road
Alengo
Google
Nov 7, 2020 2:25:46 PM
1.8496N 32.3495E
Akokoro Road
Alengo, Apac
Uganda
Alenga Roman Catholic church Apac

Alenga Roman
Catholic Church
Akokoro Road
Alengo
Google
Nov 7, 2020 2:25:55 PM
1.8496N 32.3495E
Akokoro Road
Alengo, Apac
Uganda
Alenga Roman Catholic church Apac


Nov 7, 2020 6:36:41 PM
1.8238N 32.5015E
Maruzi, Apac
Uganda
Alenga Roman Catholic church Apac
Google


Speedtest
SPEEDTEST
PING
19
DOWNLOAD
3.35
UPLOAD
3.75
GO
Airtel Uganda
Kampala
Nov 7, 2020 6:43:26 PM
1.8572N 32.4391E
Alenga Roman Catholic church Apac
Google

| | |
|---|---|
| Country | Uganda |
| Subscriber Module Mode | TDD |
| Subscriber Module Priority | Normal |
| Network Mode | Bridge |
| Downlink RSSI | -81 dBm |
| Downlink SNR | 22 dB |
| Uplink MCS | MCS 3 - 16-QAM 1/2 |
| Downlink MCS | MCS 11 - 16-QAM 1/2 |
| cnMaestro Remote Management | Enabled- The Registered AP Is Onboarded |
| cnMaestro Connection Status | Connected to 197.221.152.218 |
| cnMaestro Account ID | cnmaestro_on_premises |




Nov 7, 2020 6:43:43 PM
1.8572N 32.4391E
Alenga Roman Catholic church Apac

| | |
|---|---|
| Management VLAN | ○ Disabled ◉ Enabled |
| Management VLAN ID | 952 |
| Management VLAN Priority | |
| Management VLAN Access | ○ Wireless ◉ Ethernet and Wireless |
| Data VLAN | ○ Disabled ◉ Enabled |
| Data VLAN ID | 952 |
| Data VLAN Priority | |




Nov 7, 2020 6:44:04 PM
1.8906N 32.3767E
Alenga Roman Catholic church Apac