Image 1 (top-left)

10/100 Mbit Data
10/100 Mbit Data+Power
Power

18 Jun 2021 18:03:37
2.238260N 32.893721E
2 Aduku Road
Lira
Northern Region
Altitude:1100.7m
FINCA LIRA IDU AT client

Image 2 (top-right)

18 Jun 2021 18:16:26
2.238432N 32.893533E
Obote Avenue
Lira
Northern Region
Altitude:1096.2m
Speed:0.0km/h
FINCA LIRA ODU AT client

Image 3 (bottom-left)

20 MHz	IP Address — 172.19.139
28 dBm	Date and Time — 18 Jun 2021
30 dBi	System Uptime — 4 minutes,
Other	System Description — --
TDD	Registered AP SSID — LIRA IGANG
Normal	Registered AP MAC Address — 00:04:56:D9
Bridge	Device Coordinates — --
-58 dBm	Link Quality (Uplink) — 100 %
39 dB	Link Capacity (Uplink) — 80 %
MCS 13 - 64-QAM 2/3	Ethernet Status — 100 Mbps /
MCS 10 - QPSK 3/4	
Enabled- The Registered AP Is Onboarded	
Device Approval Pending	

18 Jun 2021 18:00:55
2.238285N 32.893715E
Obote Avenue
Lira
Northern Region
Altitude:1100.7m
FINCA LIRA LOGIN AT client

Image 4 (bottom-right)

Read-Only Community String   publik
Read-Write Community String   private
System Name   CambiumNetworks
System Description
Traps   ● Disabled ○ Enabled
Trap Community String   cambiumtrap
Server 1
Server 2

18 Jun 2021 18:01:36
2.238284N 32.893710E
Obote Avenue
Lira
Northern Region
Altitude:1100.5m
FINCA LIRA Management AT client

Image 1 (top-left)

☐ Info ☐ Notices ☐ Warnings ✔

✔ Alerts ✔ Emergency

Remote Management   ○ Disabled   ● Enabled

cnMaestro URL   http://197.221.152.218

Cambium ID   cnmaestro_on_premises

Onboarding Key   runway2020

Management

Administrator Account   Disabled   ● Enabled

Username   admin

Password   ••••

18 Jun 2021 18:01:46
2.238284N 32.893710E
Obote Avenue
Lira
Northern Region
Altitude:1100.5m
FINCA LIRA Management AT client

Image 2 (top-right)

IP Address   172.19.139.177

Subnet Mask   255.255.255.128

Gateway   172.19.139.129

Preferred DNS Server

Alternate DNS Server

Ethernet Port Security   ● Disabled   ○ Enabled

Secure MAC Limit   5

MAC Aging Time   300

(VLAN)

Management VLAN   ○ Disabled   ● Enabled

Management VLAN ID   220

18 Jun 2021 18:02:09
2.238275N 32.893692E
Obote Avenue
Lira
Northern Region
Altitude:1100.7m
FINCA LIRA Management AT client

Image 3 (bottom-left)

10/100 Mbit Data+Power

Power

IRANGA APJ
BEST RESULT SETTING G LIRA CENTRAL
TRUE MP
@-UGAFODE

18 Jun 2021 10:45:33
2.23782N 32.894319E
Obote Avenue
Lira
Northern Region
Altitude:1106.2m
Speed:0.0km/h
FINCA LIRA IDU AT SITE

Image 4 (bottom-right)

18 Jun 2021 10:21:30
2.237986N 32.894275E
Obote Avenue
Lira
Northern Region
Altitude:1108.8m
Speed:0.0km/h
FINCA LIRA ODU AT SITE

Top-left image

ver	7 dBm
ain	16 dBi
try	Uganda
de	TDD
tio	Flexible
ity	WPA2
ent	Enabled
tus	Connecting
ID	cnmaestro_on_premises

System Uptime	1 day, secon
System Description	--
Device Coordinates	--
DFS Status	In-Serv
Ethernet Status	10 Mb
Wireless Status	Up
Registered Subscriber Modules	2
Registered Elevate Subscriber Modules	0

Top-right image

Read-Only Community String	public
Read-Write Community String	private
System Name	CambiumNetworks
System Description	
System Location	
Traps	● Disabled ○ Enabled
Trap Community String	cambiumtrap

Server 1
Server 2

Bottom-left image

IP Assignment ○ Static ● DHCP

IP Address	172.17.17.169
Subnet Mask	255.255.255.192
Gateway	172.17.17.129
Preferred DNS Server	
Alternate DNS Server	

l Area Network (VLAN)

Management VLAN	○ Disabled ● Enabled
Management VLAN ID	506
Management VLAN Priority	
Ethernet MTU	1500

Bottom-right image

Remote Management	○ Disabled ● Enabled
Zero Touch	○ Disabled ● Enabled
cnMaestro URL	https://197.221.152.218
Cambium ID	cnmaestro_on_premises
Onboarding Key	runway2020

Administrator Account	Disabled ● Enabled
Username	admin
Password	●●●●●●●●
Installer Account	○ Disabled ● Enabled
Username	inst