




11 May 2021 18:40:06
 2.242566N 32.896774E
 Lira, Lira
 Uganda
 Altitude:1073.9m
 Speed:0.0km/h
 KCB LIRA ODU AT CLIENT





11 May 2021 18:22:07
 2.243157N 32.896592E
 Lira, Lira
 Uganda
 Altitude:1090.0m
 KCB LIRA IDU AT CLIENT



11 May 2021 18:28:40
 2.242803N 32.896634E
 Altitude:1063.8m
 Speed:0.0km/h
 KCB LIRA Login AT CLIENT



11 May 2021 18:29:13
 2.242819N 32.896608E
 Lira, Lira
 Uganda
 Altitude:1063.6m
 Speed:0.0km/h
 KCB LIRA Management AT CLIENT



LIRA TESO BAR AP1	Wireless MAC Address	00:04:56:D9:4A:9C
LIRA TESO BAR AP1	Ethernet MAC Address	00:04:56:D9:4A:98
5215 MHz	IP Address	172.17.91.2
20 MHz	Date and Time	01 Sep 2015, 00:31:06 GMT
10 d Transmitter Output Power: 10 dBm	System Uptime	31 minutes, 5 seconds
16 dBi	System Description	--
Uganda	Device Coordinates	--
TDD	DFS Status	Not Available
Flexible	Ethernet Status	100 Mbps / Full
WPA2	Wireless Status	Up
Enabled	Registered Subscriber Modules	0
Connecting in 2 minutes	Registered Elevate Subscriber Modules	0

11 May 2021 13:08:31
2.237842N 32.894301E
Lira, Lira
Uganda
Altitude:1104.3m
Speed:0.0km/h
KCB LIRA Login AT SITE

Read-Only Community String: public

Read-Write Community String: private

System Name: CambiumNetworks

System Description:

Traps: Disabled Enabled

Trap Community String: cambiumtrap

Server 1

Server 2

11 May 2021 13:08:55
2.237840N 32.894302E
Lira, Lira
Uganda
Altitude:1104.4m
Speed:0.0km/h
KCB LIRA Management AT SITE

Alerts: Emergency:

Remote Management: Disabled Enabled

cnMaestro URL: http://197.221.152.218

Cambium ID: cnmaestro_on_premises

Onboarding Key: runway2020

Administrator Account: Disabled Enabled

Username: admin

Password:

11 May 2021 13:09:11
2.237839N 32.894302E
Lira, Lira
Uganda
Altitude:1104.5m
Speed:0.0km/h
KCB LIRA Management AT SITE

IP Assignment: Static DHCP

IP Address: 172.17.91.2

Subnet Mask: 255.255.255.248

Gateway: 172.17.91.1

Preferred DNS Server:

Alternate DNS Server:

Local Area Network (VLAN)

Management VLAN: Disabled Enabled

VLAN ID: 657

VLAN Priority:

11 May 2021 13:09:30
2.237839N 32.894302E
Lira, Lira
Uganda
Altitude:1104.6m
Speed:0.0km/h
KCB LIRA Management AT SITE