

PREVENTIVE MAINTENANCE CHECKLIST

Client Name/ID: GLOBAL VILLAGE RESORT Date: 1/06/2021  
 Client Coordinates: 2.4511N, 81.4820E Location: PAKWACHH  
 Local Contact Personnel: KUMAKECH FRED Serving Site ID: N04020  
 Link Type: PMP Serving Site Name: PAKWACHH

Preventive Maintenance Checklist	Remark/ Comment
Condition of IDU>>ODU Cable Client end: Site end:	} GOOD
Other Equipment Condition > Client-end > Site-end	} GOOD
Type of equipment installed	FORCE 200, MIKROTIK 30
Distance of Hop	1.69km
RSSI Levels (dBm)	-78 dBm
Earthing - client end	NA
Earthing - Site Radio	NA
Airlink Quality Measure > Link Quality: > Link Capacity:	100% 15%
Status of ODU mounting at Client end & Site	GOOD
Nature of power at client end	AC 240V, 50-60Hz
Serving site Port	OSN 1/14
RJ45 connectors	GOOD TERMINATION
Share link details > Site name > Naming of Sector at site > Other clients attached.	PAKWACHH PAKWACHH PT 14 OSN AP IFMS PAKWACHH, GLOBAL VILLAGE ACCOMMODATION

Confirm link is added to CN maestro	24 - ONLINE CLIENT
Check that link management is enabled <ul style="list-style-type: none"> <li>➤ IPS/VLAN are enabled (indicate IPS and VLAN if already existing)</li> <li>➤ SNMP is enabled</li> <li>➤ Confirm successful addition on cacti</li> </ul>	ENABLED

**Client acknowledgment:**

Name: KUMAKECH FRED  
 Signature: [Signature]  
 Date: 1/06/2021

**Field Engineer:**

Name: BARAIRE ABEMERECI  
 Signature: [Signature]  
 Date: 1/06/2021